		Legionnaire	s Disease Risk	« Assessment				
Property address	Abbey	Church 4, Th	e Highland Clu	ub, St. Benedict	's Abbey, Fort	Augustus		
Date of assessment	8-1	1-22	Assessment carried out by	M. DA	ALLAS			
	Detached house	Single flat	Other					
Is there any tenant, resident or regular visitor particularly susceptible to Legionella due to age, health or lifestyle?			YE	S. ALL AG	ES STAY	ING.		
Describe type of cold-water system e.g. mains feed or from storage tank (Include sketch if possible at rear of document)			MAir	VS FED.				
Describe type of hot feed via combi boiler (Include sketch if pos	or from sto	orage tank.	MAIN	MAINS FED VIA COMBI BOILER				
			RISK CATEGORIE	S				
1. Water outlet temp Is cold water temperat outlets below 20°C? Cold water must flow from djustments need to be m Identify any	cure at Yes n outlets at be ade to the sy	stem i.e. lagging o	above 50 vater above 50°C to of pipework or adju	stment of temperat	nperatures are too ure settings for hot	water.		
Defect/Risk	WATER COULD BE TURNED UP TOO HOT AT BOILER.							
Related Recommendation	PREVENT BOILER FROM EXCEEDING 60°C							
Responsible person to carry out action	Landlord	Tenant	Other	Other Details:	ROPERTY MI	ANAGER		
2. Cold water storage	tanks			I	-			
Is there a cold water st tank present?	torage Yes	No	If No go to Q3	Does it have a tig lid?	tht fitting Yes	No		
Is the water temperatu the tank below 20°C?	ure in Yes	No		n the tank clean & s,scale & organic n		No		
Is the tank insulated?	Yes	No	Location of tank					
fany debris etc. is presen ank may need to be repla hould be below 20°C & th Identify any Defect/Risk	iced. All cold	water tanks shou	ld have tight fitting	g lids to prevent deb				
Related Recommendation								
Responsible person to carry out action	Landlord	Tenant	Other	Other Details:				
3. Hot water					_			
Is the temperature set the hot water is heater				n that	Yes	No No		
IB: If the temperature is sank should be set and ma	intained at 6	50°C.						
Identify any Defect/Risk				UP TOO HO		ILER		
Related Recommendation	PREVER	IT BOILE	er From	EXCEEDIN(4 60°C			
Responsible person to	Landlord	Tenant	Other	Other Potails:	PERFERTY N	1ANAGER		

4. Little used outlets							
Are there any water o bathrooms? If yes, ide					per wee	k e.g. in	n guest Yes No
Details POSSABILIT	y of	SHOW	HER OR	TAR	SIN	GV6	ST ROOM NOT BEING USED
750							h the outlet for at least 5 minutes. Aerosol production
Identify any	[ACK		US _t		vater ion	ger at a	lower pressure to avoid aerosols.
Defect/Risk			1377 1315		~~	0.11	0-1-10
Related Recommendation	CLEAN		TO H	.VSH '	THKOU	GH	AFTER EACH VISIT
Responsible person to carry out action	Landlord		Tenant		Other	\checkmark	Other PROPERTY MANAGER Details:
5. Shower heads	,						
Are there any showers					tlet & lo	cation b	below Yes \ No
ONE IN Details	EACH	BAT	PROC	M.			
	eaned, disir	fected a	nd desca	led at lea	st once e	very 6 m	nonths. Aerosol production should be minimised
during this process. Identify any Defect/Risk	SHOW	ER H	4CAD	3			
Related Recommendation	REMOV	E 001	HEN	NOT	IN C	BE,	, DRINFECT TWICE YEARLY
Responsible person to carry out action	Landlord		Tenant		Other	$\sqrt{}$	Other PROPERTY MANAGER
Are there any dead leg	gs in the pro	operty?	If yes, id	entify o	utlet & l	ocation	d legs known in the system? below Yes No flows through all pipework regularly.
Related							
Recommendation Responsible person to	Landlord		Tenant		Other		Other
7. Unoccupied proper	ties						Details:
Is the property left und the summer holiday or	occupied fo			e, e.g. in	the case	eof stuc	dent lettings over Yes No
							ast 5 minutes when unoccupied & prior to re-occupation consider draining the system.
Identify any Defect/Risk	EMPTY	PR	OPER	TES	OUR	ing	QUET PERIODS
Related Recommendation	FLUSH	WE	EKLY	1			
Responsible person to carry out action	Landlord		Tenant	•	Other	\checkmark	Other PROPERTY MANAGER
Advice to tenants (This ca							
Has advice been giver Disease in a domestic	setting and	their re	esponsib	ilities to	minimis	se risk?	Yes No N/A*Short term lets
							if any information changes. You should ensure
that the recommendation Signed	ons above		lemente	and a	ny existi	ing com	Date 8 11 22
Print Name	MARK	DA.	ISAS	V -			

SKETCH OF WATER SYSTEM 3 BED. MAINS FED COMBI BOILER.

