		Legionnaires	Disease Ris	k Assessmer	11		
Property address	Abbey	Church 10, Th	ne Highland (	Club, St. Bene	edict's Abbe	y, Fort A	ugustus
Date of assessment	8-1	1-22	Assessment carried out b	M.	DALLAS		
	Detached house	Single flat	Other				
Is there any tenant, r particularly susceptib health or lifestyle?	YE	S. ALL	AGES S	STAYIN	19.		
Describe type of cold mains feed or from so (Include sketch if pos	MAI	INS FED.					
Describe type of hot feed via combi boiler (Include sketch if pos	orage tank.	Mair	IS FED	FED VIA COMBI BOILER			
		ı	RISK CATEGORI	ES			
1. Water outlet temp Is cold water temperat outlets below 20°C? Cold water must flow from djustments need to be m Identify any	ture at <b>Yes</b> n outlets at be ade to the sy	stem i.e. lagging o	above 5 ater above 50°C t f pipework or adj	ustment of tempe	f temperatures erature settings	are too low for hot wat	er.
Defect/Risk	WATE	R COULD &	SE TURN	ED UP			BOILEK.
Related Recommendation	PREVE	NT BOILE	R FROM	EXCEEDIN	19 60	$^{\circ}C$	
Responsible person to carry out action	Landlord	Tenant	Other	Other Details:	PROFERTY	MAN	AGER
2. Cold water storage	tanks			ī			
Is there a cold water stank present?	orage <b>Yes</b>	No ,	If No go to Q3	Does it have a lid?	a tight fitting	Yes	No
Is the water temperatu the tank below 20°C?	ire in <b>Yes</b>	No		in the tank clear ris,scale & organ		Yes	No
Is the tank insulated?	Yes	No	Location of tank				
f any debris etc. is presen ank may need to be repla hould be below 20°C & th Identify any Defect/Risk Related	ced. All cold	water tanks shoul	d have tight fittin	g lids to prevent	debris entering		
Recommendation							
Responsible person to carry out action	Landlord	Tenant	Other	Other Details:			
3. Hot water		2.89					<b>.</b>
Is the temperature set the hot water is heated IB: If the temperature is sank should be set and ma	d to and sto et at above t	red at a tempera 50°C this can cause	ture of 60°C?		Youre setting on th	V	No dor hot water
Identify any Defect/Risk	BOILER	(OULD BE	TURNED	UP TOO H	10T AT	BOIL	ER
Related Recommendation	PREVER	JT BOILE	R FROM	EXCEEDIT	NG 60	°C	
Responsible person to	Landlord	Tenant	Other	Other Details:	PRIPERT	Y MAI	VAGER

4. Little used outlets								
Are there any water o bathrooms? If yes, ide					per wee	k e.g. in	n guest Yes No	
Details POSSABILIT	y of	SHOW	HER OR	TAR	SIN	GV6	ST ROOM NOT BEING USED	
750							h the outlet for at least 5 minutes. Aerosol production	
Identify any	[ACK		US <sub>t</sub>		vater ion	ger at a	lower pressure to avoid aerosols.	
Defect/Risk			1377 1315		~~	0.11	0-1-10	
Related Recommendation	CLEAN		TO H	.VSH '	THKOU	GH	AFTER EACH VISIT	
Responsible person to carry out action	Landlord		Tenant		Other	$\checkmark$	Other PROPERTY MANAGER  Details:	
5. Shower heads	,							
Are there any showers					tlet & lo	cation b	below Yes   \ No	
ONE IN Details	EACH	BAT	PROC	M,				
	eaned, disir	fected a	nd desca	led at lea	st once e	very 6 m	nonths. Aerosol production should be minimised	
during this process. Identify any Defect/Risk	ntify any Church LIGARS							
Related Recommendation	REMOV	E 001	HEN	NOT	IN C	BE,	, DRINFECT TWICE YEARLY	
Responsible person to carry out action	Landlord		Tenant		Other	$\sqrt{}$	Other PROPERTY MANAGER	
Are there any dead leg	gs in the pro	operty?	If yes, id	entify o	utlet & l	ocation	d legs known in the system? below Yes No flows through all pipework regularly.	
Related								
Recommendation Responsible person to	Landlord		Tenant		Other		Other	
<ul><li>7. Unoccupied proper</li></ul>	ties						Details:	
Is the property left und the summer holiday or	occupied fo			e, e.g. in	the case	eof stuc	dent lettings over Yes No	
							ast 5 minutes when unoccupied & prior to re-occupation consider draining the system.	
Identify any Defect/Risk	EMPTY	PR	OPER	TES	OUR	ing	QUET PERIODS	
Related Recommendation	FLUSH	WE	EKLY	1				
Responsible person to carry out action	Landlord		Tenant	•	Other	$\checkmark$	Other PROPERTY MANAGER	
Advice to tenants (This ca								
Has advice been giver Disease in a domestic	setting and	their re	esponsib	ilities to	minimis	se risk?	Yes No N/A*Short term lets	
							if any information changes. You should ensure	
that the recommendation Signed	ons above		lemente	and a	ny existi	ing com	Date 8 11 22	
Print Name	MARK	DA.	ISAS	V -				

SKETCH OF WATER SYSTEM 2 BED. MAINS FED COMBI BOILER

