		Legionnaires	Disease Risk A	issessment				
Property address	Courtyard (Cottage 3, The Highland C	Club, St. Benedict's Abbey, Fo	ort Augustus PH32 4DE				
Date of assessment	8-1	1-22	Assessment carried out by	M. DA	J. DALLAS			
Describe property type	Detached house	Single flat	Other					
Is there any tenant, r particularly susceptib health or lifestyle?		_	YES	ALL AGE	ES STAY	ING.		
Describe type of cold- mains feed or from so (Include sketch if pos	torage tank		MAINS	S FED				
Describe type of hot feed via combi boiler (Include sketch if pos	or from sto	orage tank.	MAINS	MAINS FED VIA COMBI BOILER				
		F	RISK CATEGORIES					
1. Water outlet temp Is cold water temperat outlets below 20°C? Cold water must flow from djustments need to be m Identify any	cure at Yes n outlets at be ade to the sy	stem i.e. lagging of	above 50°C ater above 50°C to m	inimise risk. If tem nent of temperatur	peratures are too I	water.		
Defect/Risk Related						DUILER		
Recommendation	PREVE	NT BOILE	R FROM E	XCEEDINY	60°C			
Responsible person to carry out action	Landlord	Tenant	Other	Other Details:	OFERTY MA	ANAGER		
2. Cold water storage	11				_			
Is there a cold water st tank present?	orage Yes	No	If No go D to Q3 lie	oes it have a tighd?	t fitting Yes	No		
Is the water temperature in Yes the tank below 20°C?		No		Is water in the tank clean & free of Yes rust, debris, scale & organic matter?				
Is the tank insulated?	Yes	No	Location of tank					
f any debris etc. is presen ank may need to be repla hould be below 20°C & th Identify any Defect/Risk Related	ced. All cold	water tanks should	d have tight fitting lid	ls to prevent debri				
Recommendation								
Responsible person to carry out action	Landlord	Tenant	Other	Other Details:				
3. Hot water					_			
Is the temperature set the hot water is heated IB: If the temperature is so ank should be set and ma	d to and sto	red at a tempera 60°C this can cause	ture of 60°C?		Yes tting on the boiler	and/or hot water		
Identify any Defect/Risk			TURNED U			ILER		
Related Recommendation	PREVER	JT BOILER	PROM BY	KCEEDING	60°C			
Responsible person to	Landlord	Tenant	Other	Other PK	PUPERTY M	IANAGER		

4. Little used outlets							
Are there any water o bathrooms? If yes, ide					per wee	k e.g. in	n guest Yes No
Details POSSABILIT	y of	SHOW	HER OR	TAR	SIN	GV6	ST ROOM NOT BEING USED
750							h the outlet for at least 5 minutes. Aerosol production
Identify any	[ACK		US _t		vater ion	ger at a	lower pressure to avoid aerosols.
Defect/Risk			1377 1315		~~	0.11	0-1-10
Related Recommendation	CLEAN		TO H	.VSH '	THKOU	GH	AFTER EACH VISIT
Responsible person to carry out action	Landlord		Tenant		Other	\checkmark	Other PROPERTY MANAGER Details:
5. Shower heads	,						
Are there any showers					tlet & lo	cation b	below Yes \ No
ONE IN Details	EACH	BAT	PROC	M,			
	eaned, disir	fected a	nd desca	led at lea	st once e	very 6 m	nonths. Aerosol production should be minimised
during this process. Identify any Defect/Risk	SHOW	ER H	4CAD	3			
Related Recommendation	REMOV	E 001	HEN	NOT	IN C	BE,	, DRINFECT TWICE YEARLY
Responsible person to carry out action	Landlord		Tenant		Other	$\sqrt{}$	Other PROPERTY MANAGER
Are there any dead leg	gs in the pro	operty?	If yes, id	entify o	utlet & l	ocation	d legs known in the system? below Yes No flows through all pipework regularly.
Related							
Recommendation Responsible person to	Landlord		Tenant		Other		Other
7. Unoccupied proper	ties						Details:
Is the property left und the summer holiday or	occupied fo			e, e.g. in	the case	eof stuc	dent lettings over Yes No
							ast 5 minutes when unoccupied & prior to re-occupation consider draining the system.
Identify any Defect/Risk	EMPTY	PR	OPER	TES	OUR	ing	QUET PERIODS
Related Recommendation	FLUSH	WE	EKLY	1			
Responsible person to carry out action	Landlord		Tenant	•	Other	\checkmark	Other PROPERTY MANAGER
Advice to tenants (This ca							
Has advice been giver Disease in a domestic	setting and	their re	esponsib	ilities to	minimis	se risk?	Yes No N/A*Short term lets
							if any information changes. You should ensure
that the recommendation Signed	ons above		lemente	and a	ny existi	ing com	Date 8 11 22
Print Name	MARK	DA.	ISAS	V -			

SKETCH OF WATER SYSTEM 2 BED. MAINS FED COMBI BOILER

